



A/C Type : N/A  
 A/C Registration : N/A  
 Reason for BSI :Assessment

Model : JT15D-5  
 A/C MSN : N/A  
 ESN : PCE-JA0147  
 TSN:3062:45

Location : DEL  
 Position:GRD  
 Performed By:Vikas Joshi  
 CSN:2433



REF AMM 72-00-00	LP BOOSTER BLADES
<p><b>CONDITION:</b>                  Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                  Acceptable as per AMM.                  Serviceable as is.</p>	

REF AMM 72-00-00	LP STATOR VANES
<p><b>CONDITION:</b>                  Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                  Acceptable as per AMM.                  Serviceable as is.</p>	

A/C Type : N/A  
 A/C Registration : N/A  
 Reason for BSI :Assessment

Model : JT15D-5  
 A/C MSN : N/A  
 ESN : PCE-JA0147  
 TSN:3062:45



Location : DEL  
 Position:GRD  
 Performed By:Vikas Joshi  
 CSN:2433

REF AMM 72-00-00	HP IMPELLER
<p><b>CONDITION:</b>                      Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                      Acceptable as per AMM.                      Serviceable as is.</p>	
REF AMM 72-00-00	COMBUSTION CHAMBER
<p><b>CONDITION:</b>                      Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                      Acceptable as per AMM.                      Serviceable as is.</p>	

A/C Type : N/A  
 A/C Registration : N/A  
 Reason for BSI :Assessment

Model : JT15D-5  
 A/C MSN : N/A  
 ESN : PCE-JA0147  
 TSN:3062:45



Location : DEL  
 Position:GRD  
 Performed By:Vikas Joshi  
 CSN:2433

REF AMM 72-00-00	FUEL NOZZLES
<p><b>CONDITION:</b>                      Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                      Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
REF AMM 72-00-00	LARGE EXIT DUCT
<p><b>CONDITION:</b>                      Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                      Acceptable as per AMM.                      Serviceable as is.</p>	

A/C Type : N/A  
 A/C Registration : N/A  
 Reason for BSI :Assessment

Model : JT15D-5  
 A/C MSN : N/A  
 ESN : PCE-JA0147  
 TSN:3062:45


Location : DEL  
 Position:GRD  
 Performed By:Vikas Joshi  
 CSN:2433

REF AMM 72-00-00	SMALL EXIT DUCT
<p><b>CONDITION:</b>            Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>            Acceptable as per AMM.            Serviceable as is.</p>	
REF AMM 72-00-00	HPT BLADES
<p><b>CONDITION:</b>            Observed nonmeasurable dent on trailing edge ,towards tip area of QTY-02 blades. Also contamination observed with heavy enviromantal deposit, through out the stage, Nil significant findings.</p>	
<p><b>DISPOSITION:</b>            Acceptable as per AMM.            Serviceable as is.</p>	

A/C Type : N/A  
 A/C Registration : N/A  
 Reason for BSI :Assessment

Model : JT15D-5  
 A/C MSN : N/A  
 ESN : PCE-JA0147  
 TSN:3062:45

Location : DEL  
 Position:GRD  
 Performed By:Vikas Joshi  
 CSN:2433

REF AMM 72-00-00	LPT STAGE 2 BLADES
<p><b>CONDITION:</b>                      Contamination observed with heavy enviromantal deposit.Nil significant findings.</p>	
<p><b>DISPOSITION:</b>                      Acceptable as per AMM.                      Serviceable as is.</p>	



VIDEO BOROSCOPE INSPECTION OF ENGINE JT15D-5 REPORT

A/C Type : N/A  
 A/C Registration : N/A  
 Reason for BSI :Assessment

Model : JT15D-5  
 A/C MSN : N/A  
 ESN : PCE-JA0147  
 TSN:3062:45

Location : DEL  
 Position:GRD  
 Performed By:Vikas Joshi  
 CSN:2433

ADDITIONAL COMMENTS AND PICTURES:



VIDEO BOROSCOPE INSPECTION OF ENGINE JT15D-5 REPORT

A/C Type : N/A  
A/C Registration : N/A  
Reason for BSI :Assessment

Model : JT15D-5  
A/C MSN : N/A  
ESN : PCE-JA0147  
TSN:3062:45

Location : DEL  
Position:GRD  
Performed By:Vikas Joshi  
CSN:2433





VIDEO BOROSCOPE INSPECTION OF ENGINE JT15D-5 REPORT

A/C Type : N/A  
A/C Registration : N/A  
Reason for BSI :Asessment

Model : JT15D-5  
A/C MSN : N/A  
ESN : PCE-JA0147  
TSN:3062:45

Location : DEL  
Position:GRD  
Performed By:Vikas Joshi  
CSN:2433

**Summary**

1. Performed VBSI as per below mention references :-	
TASK	Limitation
ENGINE BORESCOPE INSPECTION    REF. AMM 72-00-00	Nil

**Result**

**Engine internal hardware condition is satisfactory as per AMM. Engine water wash is recommended.**

ALL BORESCOPE PLUGS REINSTALLED BY OMNISCIENT AVIATORS INSPECTIONS EMPLOYEE: YES  NO

THIS REPORT & THE ACCOMPANYING VIDEO IS SUBMITTED SUBJECT TO THE CONDITION THAT IS UNDERSTOOD & AGREED THAT THE CONTENTS ARE BASED ON DILIGENT INSPECTION & ARE EXCLUSIVE OF LATENT DEFECTS IN MATERIALS, RIGGING OR SYSTEMS NOT DETECTABLE WITHOUT REMOVAL OR DISASSEMBLY; BUT ARE BELIEVED TO BE CORRECT & FAIRLY REPRESENTATIVE OF THE CONDITION OF THE ENGINE. THIS SURVEY IS SUBMITTED WITHOUT PREJUDICE & IN CONFIDENCE TO THE NAMED CLIENT & IS WITHOUT RESPONSIBILITY TO OTHERS TO WHOM IT MAY BE SHOWN.

DATE - 26/08/2025

Report prepared by

Vikas Joshi