



Piper Aircraft, Inc.
 2926 Piper Drive
 Vero Beach, FL, U.S.A. 32960

SERVICE SPARES LETTER

NO. 470

Date: June 28, 2016

(M)

SUBJECT:

FUEL SENDER UPGRADE

MODELS AFFECTED:

PA-31/PA-31-300/-325 Navajo
 PA-31-350 Chieftain/T-1020
 PA-31P Pressurized Navajo

SERIAL NUMBERS AFFECTED:

31-1 through 31-861; 31-7300901 through 31-8312019
 31-5001 through 31-5004;
 31-7305005 through 31-8553002
 31P-1 through 31P-80;
 31P-7300110 through 31P-7730012

PURPOSE:

This service spares letter announces the availability of an improved replacement fuel quantity sender for the affected models.

AVAILABILITY OF PARTS:

Your Factory Authorized Piper Service Facility

SUMMARY:

The table below cross-references the prior Piper part numbers with the new, improved replacement part numbers (New Part Number) and identifies the correct locations for each of the four fuel quantity senders.

Old Part Number	New Part Number	Position
550-695 (40648-002)	PS50149-2	Main Outboard LH/RH
550-696 (40648-003)	PS50149-3	Main Inboard LH/RH
550-697 (40648-004)	PS50149-4	Auxiliary Outboard LH/RH
550-698 (40648-005)	PS50149-5	Auxiliary Inboard LH/RH

NOTE:

Please notify the factory of any address/ownership corrections. Changes should include aircraft model, serial number, and current owner's name and address.

Corrections and/or changes should be directed to:

PIPER AIRCRAFT, INC.
 Attn: Customer Service
 2926 Piper Drive
 Vero Beach, FL 32960